UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,941,420 B2

Page 1 of 1

APPLICATION NO.: 10/080488

DATED

: September 6, 2005

INVENTOR(S)

: Henry Esmond Butterworth et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9

Line 10, "The LISA controller" should read -- the LSA controller --

Signed and Sealed this

Twenty-first Day of November, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office